

## **IM-XVIYRA**

Interpretations by the technical committee valid from January 1st 2020

2014: If the bulkhead is constructed so that feet can go through it, the cleat must be easily releasable from that position as well in case of emergency.

2014: A locking halyard mechanism is allowed under 3.8.3

2015: The newly developed cardanic/bike chain steering mechanism is allowed under 3.8.3

2017: The fore and aft position of the mast on the ball is optional. A mast base fitting that allows for adjustment of this position between races is allowed under specification 3.8.3

2018: In the monotype, the only allowed way the sailors can adjust luff tension while sailing is through sheet movement. No other fittings to achieve that goal are allowed.

2018 For all measuring purposes, a (re)movable/interchangeable mast socket shall be in the position that makes the mast as long as it can possibly be.

2019 In 3.6.5 the middle girth is measured from the mid point on the leech to the mid point on the luff, including boltrope. The top girth is measured from the 3/4 point on the leech to the 3/4 point on the luff, including boltrope.